Brazing Seminar

Thursday, November 19, 2026

TOPICS

- Safety Overview
- Proper Techniques
- Handouts and Materials
- Hands-on Lab Project

PLEASE NOTE - LAB SAFETY

1. Proper attire required.
2. No shorts or cut-offs of any kind.
3. No open-toed or open-heel footwear will be worn in the lab. Steel-toed shoes are recommended. High-heeled shoes are not allowed in the lab.

For more information, please see link below for Lab Safety / Safe Work Practices:
https://www.iuoe399.org/education/labclass-safety-form/

MORNING SESSION
Time:
Check-in begins: 8:30 a.m.
Seminar: 9:00 a.m.-12:30 p.m.

AFTERNOON SESSION
Time:
Check-in begins: 3:30 p.m.
Seminar: 4:00 p.m.-7:30 p.m.

Place:
IUOE Local 399 Office and Training Center
2260 S Grove Street
Chicago IL 60616 Parking Available

Class Fee:

Contributing Member:	No Fee
Non-Contributing Member:	$50
Non-Member Fee:	$100

Any Questions Contact: Education Department at 312-372-9870 Ext. 4000
Seating is Limited, Pre-Registration is Required
Download Registration form at www.iuoe399.org